









**ALLWEDD/KEY**

-  Cilfachau parcio arfaethedig  
Proposed Parking bays
-  Gorchymyn Dim Aros ar Unrhyw Adeg arfaethedig  
Proposed Prohibition of Waiting At Any Time
-  Llinellau dwbl melyn presonnol i gael ei symud  
Existing double yellow lines to be removed
-  Llinellau melyn dwbl presennol i aros  
Existing double yellow lines to remain
-  Croesfan presennol i aros  
Existing Crossing to remain
-  Palmant ollwng presennol i aros  
Existing Drop Kerb to remain
-  Briffordd heb ei fabwysiadu  
Unadopted Highway

**FFYRDD AMRYWIOL/VARIOUS ROADS TAFFS WELL  
ADOLYGIAD PARCIO/PARKING REVIEW**

|   |                   |   |   |                         |              |       |     |
|---|-------------------|---|---|-------------------------|--------------|-------|-----|
| Group Director<br>Environmental Services<br>Rhondda Cynon Taf<br>County Borough Council<br>Sardis House, Sardis Road<br>Pontypridd, CF37 1DU. |                   |  | Cyfarwyddwr Cyfadran y<br>Gwasanaethau Amgylchedd<br>Cyngor Bwrdeistref Sirol<br>Rhondda Cynon Taf<br>Ty Sardis, Sardis Road<br>Pontypridd, CF37 1DU. |                         | Size Maint   | A3    |     |
|   |                   |   | Drawn Tynnu   | JG                      |              |       |     |
|   |                   |   | Checked Gwrio   | AMC                     |              |       |     |
|   |                   |   | Approved Cymradwyo  | TP                      |              |       |     |
|   |                   |   | Date Dyddiad  | 28/12                   |              |       |     |
| File No. Rhif y feil  | IF 066            | Scale Graddfeydd  | N. T. S   | Drg. No. Rhif y cynllun | T2017/123/1a |       |     |
| Rev No.   | Amendment Details |   |   | Date                    | Made         | Check | App |